

Beaver Township – Cunningham Road



Problem: The existing 30" stream crossing pipe was too small. This crossing did not have headwalls or endwalls, which caused the road, road bank and berm to erode into stream. A lack of cross pipes on the hill leading to stream, caused runoff to erode the road berm and carry sediment directly to stream.

Solution: This project increased the size of the stream crossing pipe to 48". A cross pipe was added midway up the hill. Headwalls and endwalls were installed on all pipes. A stone filter was installed at the outlet of the cross pipe.

