

Oliver Township – Mauk Hill Road

This was a Low Volume Road (LVR) Project.



Problem: Excessive water was flowing in the ditches, causing erosion near the inlets and outlets of the existing crosspipes. The road base was soft from the excessive water and was causing the tar and chip to break up.

Solution: Additional crosspipes with headwalls and endwalls were installed. The bank was graded to encourage sheet flow. French mattresses and new turn outs were installed.