

Bell Township – Beacon Road



Problem: Severe drainage problems were corrected in 2015, the first phase of this project.

Solution: This was the second phase of the project, where Driving Surface Aggregate (DSA) was placed to cap the shale used to build up the road in the first phase of the project.