

McCalmont Township – Team Road



Problem: Water from two gas well access roads was causing high velocity runoff in the existing ditches. The road was entrenched and acting as a ditch. The water was all being directed to one area, causing severe erosion.

Solution: Numerous efforts were made to prevent runoff from concentrating on the roadway and its ditches, including: the installation of additional crosspipes, the construction of grade breaks on the gas well access roads, the development of a grassy water way, building up the road base with shale, cleaning out and stabilizing existing turnouts and installing new turnouts.