

Ringgold Township – Reed Road



Problem: The existing stream crossing was too small for the water flow during heavy rain events. There was erosion on both the inlet and outlet of the pipe. The road material was washing into the stream.

Solution: A bottomless arch pipe was installed. The banks were stabilized with rip rap. The road was graded and reshaped.