

Young Township – Setree Road



Problem: The number of existing cross pipes was inadequate, causing the road base to become saturated. Existing tree canopy cover was heavy, also contributing to the saturated road. Sediment was flowing from ditches directly into the stream at the bottom of hill. Road banks were eroding into the inlets of the existing cross pipes.

Solution: Additional cross pipes were installed. Inlet boxes were installed on their sides to help stabilize the road banks surrounding the new cross pipe inlets. Some trees were removed to provide daylight on the road. The road base was built up and turn outs were added to encourage runoff to leave the roadway.

