

Young Township – Young Road



Problem: Existing road ditches were saturated. The outlet banks were eroded. Water was concentrating in one area, causing wet areas along the side of the road. Runoff from an existing gas well access road was overwhelming the Township road ditch, causing flooding.

Solution: New crosspipes were installed. The outlet banks were stabilized. An underdrain was installed. The banks were graded for sheet flow and the road surface was stabilized with DSA. The gas company installed a stone waterway on their road to divert the runoff from their road away from the Township road.

